

UNITED STATES ENVIRONMENTAL PROTEC

REGION VI INTERFIRST TWO BUILDING BOILELM STREE SUPERFUND BRANCH DALLAS TEXAS 75270

June 18, 1986

MEMORANDUM

SUBJECT: Review of FIT/3012 Site Reports

FROM: Gerald Fontenot, Chief

Field Response Section (6E-EF)

T0: Martha McKee, Chief

Site Assessment Section (6H-ES)

It has been determined in accordance with CERCLA, Section 104(b) and 300.65 of the NCP that these sites do not appear to warrant an immediate removal action at this time. When and if a site on this list does appear to fulfill the immediate removal criteria, the Emergency Response Branch should be notified immediately. Those sites marked with "*" contain references to recommended additional FIT investigaton. We will be interested in any further reports that enable us to more adequately assess those sites.

	N. E. R. Data, Blytheville, AR	No	Hazit Number
	Helena Chemical Company	AR	2160
	Crawford County Landfill, #1	AR	2526
*	Gleason's Crater Site	LA	0051
	Sun Refining and Marketing OKD058078775	OK	1911
*	Continental Oil Company	0K	4235
	Femco Services, Inc.	OK	5151
*	Unidentified Site, Pleasant Grove, TX	TX	7536
*	U. S. Gypsum	TX	10022
	J. E. Flanagan Site	TX	12408
	Berwind Railroad	TX	18325

Attachments

SUPERFUND FILE

AUG 27 1992

REORGANIZL

EMERGENCY RESPONSE PRELIMINARY ASSESSMENT COMMENTS

FIT: Date 6/13/86 TDD# 186-8500-23
Date Received: 6/16/86
Site name: Son Rofening + Marketeng
COMMENTS: FIT somologo inspection
As a number of the second of t
compared in form new well
Sen again
Recommended Action: 10 E CB action
panned
Memo Referrals: SF RCRA TSCA WAT AIR PERMITS ORC CDC STATE Other
OSC: 7 Salari DATE: 6 117186